




Motores eléctricos

De corriente continua (DC)

De corriente alterada


TYPES OF WINDINGS



1. **Conductor.** A length of wire which takes active part in the energy-conversion process is called a conductor.
2. **Turn.** One turn consists of two conductors.
3. **Coil.** One coil may consist of any number of turns.
4. **Coil –side.** One coil with any number of turns has two coil-sides.


LAP winding


- No. of parallel paths = No. of poles = No. of brushes
- No need of dummy coils
- High current low voltage
- No. of commutator segments = No. of armature slots




Wave winding

- No. of parallel paths = 2 = No. of brushes
- Dummy coils are required (Mech balance)
- High voltage low current
- No. of commutator segments = No. of







Numa revolução o
fluxo apanhado por
um condutor é

P = Number of poles of the machine.

ϕ = Flux per pole in Wb

Z = Total number of armature conductors.

N = Speed of armature in *rpm*

A = Number of parallel paths in the armature winding.

$$= P\phi \text{ Wb}$$

$$e = \frac{P\phi}{t} = \frac{P\phi}{60 / N} = \frac{P\phi N}{60} \text{ volt}$$

$$E = \frac{p\phi N}{60} \times \frac{Z}{A} = \frac{PZ\phi N}{60A} \text{ volt}$$

$$E = \frac{PZ\phi n}{A} \text{ where } n \text{ in speed in } r.p.s.$$

Tempo de uma
revolução



$$n = \frac{N}{60}$$

Para uma dada máquina o nº de polos e nº de condutores por caminho paralelo é constante

$$E = K \phi n \text{ where } K = \frac{PZ}{A} \text{ is a constant or } E \propto \phi n$$

$$E = K_1 \phi N \text{ where } K_1 = \frac{PZ}{60A} \text{ is another constant or } E \propto \phi N$$

$$E \propto \phi \omega \text{ where } \omega = \frac{2\pi N}{60} \text{ is the angular velocity in radian/second}$$

Conclui-se que a força electromotriz induzida é proporcional ao fluxo por polo e à velocidade de rotação


Se a máquina trabalha como gerador

$$E_g = \frac{PZ\phi N}{60A} \text{ volt.}$$

Se a máquina trabalha como motor

$$E_b = \frac{PZ\phi N}{60A} \text{ volt.}$$

Binário



P = No. of poles.

ϕ = Flux per pole in Wb.

r = Average radius of armature in metre.

l = Effective length of each conductor in metre.

Z = Total armature conductors.

I_a = Total armature current.

A = No. of parallel paths.

Average force on each conductor, $F = Bil$ newton

Torque due to one conductor = $F \times r$ newton metre

Total torque developed in the armature,

$$T = ZFr \text{ newton metre}$$

or

$$T = ZB i l r$$

$$E_g = \frac{PZ\phi N}{60A} \text{ volt.}$$

$$EI_a = \omega T \quad \text{or} \quad EI_a = \frac{2\pi N}{60} \times T$$

$$\text{or} \quad \frac{\phi ZNP}{60A} \times I_a = \frac{2\pi N}{60} \times T \quad \text{or} \quad T = \frac{PZ \phi N}{2\pi A} \text{ Nm}$$

An eight pole lap wound DC generator has 960 conductors, a flux of 40 m Wb per pole and is driven at 400 rpm. Find OC emf.

Solution:

$$\text{Open circuit emf, } E_g = \frac{\phi ZNP}{60A}$$

where, $\phi = 40 \text{ m Wb} = 40 \times 10^{-3} \text{ Wb}$; $Z = 960$; $N = 400 \text{ rpm}$; $P = 8$

$$A = P = 8 \text{ (lap winding)}$$

$$\therefore E_g = \frac{40 \times 10^{-3} \times 960 \times 400 \times 8}{60 \times 8} = 256 \text{ V (Ans.)}$$

The induced emf in a DC machine is 220 volts at a speed of 1500 rpm. Calculate the electromagnetic torque developed at an armature current of 20 A.

Solution:

Here $E = 220$ V; $N = 1500$ rpm; $I_a = 20$ A


Power developed in the armature

$$\omega T_e = E_b I_a$$

or
$$T_e = \frac{E_b I_a}{\omega} = \frac{E_b I_a}{2\pi N / 60} = \frac{220 \times 20 \times 60}{2\pi \times 1500} = 23.87 \text{ Nm (Ans.)}$$

1. Separately excited DC generators
2. Self excited DC generators – these are further classified as:
 - (i) Shunt wound DC generators
 - (ii) Series wound DC generators
 - (iii) Compound wound DC generators.
 - (a) Long shunt compound wound generators
 - (b) Short shunt compound wound generators.

Excitação separada



$$I_a = I_L.$$


Terminal voltage, $V = E_g - I_a R_a$

If contact brush drop per brush (v_b) is known,

$$V = E_g - I_a R_a - 2 v_b.$$

Power developed = $E_g I_a$;

Power output = $VI_L = VI_a$




$$I_{sh} = V/R_{sh}$$

$$\text{Armature current, } I_a = I_L + I_{sh}$$

$$\text{Terminal voltage, } V = E_g - I_a R_a$$

$$\text{Including brush contact drop, } V = E_g - I_a R_a - 2v_b$$

$$\text{Power developed} = E_g I_a; \text{ Power output} = VI_L$$



Series field current,

$$I_{se} = I_L = I_a \dots (4.21)$$

Series field winding resistance = R_{se}

Terminal voltage,

$$V = E_g - I_a R_a - I_{se} R_{se} = E_g - I_a (R_a + R_{se})$$

Including brush contact drop,

$$V = E_g - I_a (R_a + R_{se}) - 2v_b$$

Power developed = $E_g I_a$; Power output = $V I_L = V I_a$

Regulação de tensão num gerador shunt

Generated voltage or voltage at the terminals at no-load

$$E_g = E_0 \frac{P\phi ZN}{60A}$$

At full load, the terminal voltage is


$$V = E_g - I_{a(fl)} R_a - V_b$$

Where, $I_{a(fl)}$ = Full-load armature current

R_a = Armature resistance

V_b = Total voltage drop at the brushes

$$\% \text{ Voltage regulation} = \frac{E_0 - V}{V} \times 100$$



The armature of a four-pole DC shunt generator has 378 wave connected conductors. The armature and shunt winding resistance of the generator is 1 ohm and 100 ohm respectively. The flux per pole is 0.02 Wb. If a load resistance of 10 ohm is connected across the armature terminals and the generator is driven at 1000 rpm, calculate the power absorbed by the load.

$$\text{Generated emf, } E_g = \frac{PZ\phi N}{60 A} = \frac{4 \times 378 \times 0.02 \times 1000}{60 \times 2} = 252 \text{ V}$$

$$\text{Line current, } I_L = \frac{V}{R_L} = \frac{V}{10} \text{ (where } V \text{ is terminal voltage)}$$

$$\text{Shunt field current, } I_{sh} = \frac{V}{R_{sh}} = \frac{V}{100}$$

$$\text{Armature current, } I_a = I_L + I_{sh} = \frac{V}{10} + \frac{V}{100} = (0.11 V)$$

$$\text{Using the relation, } E_g = V + I_a R_a;$$


$$252 = V + 0.11 V \times 1.0$$

$$\therefore \text{ Terminal voltage, } V = 227 \text{ volt}$$


$$\therefore \text{ Load current, } I_L = \frac{V}{R_L} = \frac{227}{10} = 22.7 \text{ A}$$

$$\text{Power absorbed by the load, } P = VI_L = 227 \times 22.7 = 5.153 \text{ kW (Ans.)}$$


Motores DC



O comutador




(a) Torque development due to alignment of rotor field with main field



(b) Production of E_b

$$E_b = \frac{PZ\phi N}{60 A} \quad \longrightarrow \quad E_b \propto \phi N$$



$$E_b = V - I_a R_a$$

$$I_a = \frac{V - E_b}{R_a}$$

Se o motor for sujeito a um esforço com uma carga, a velocidade diminui, o que faz reduzir a força contra-electromotriz, pelo que a corrente fornecida ao motor aumenta

binário

$$EI_a = \omega T_e$$

or


$$EI_a = \frac{2\pi N}{60} \times T_e$$

or

$$\frac{\phi ZNP}{60A} \times I_a = \frac{2\pi N}{60} \times T_e$$

or

$$T_e = \frac{PZ\phi N}{2\pi A} \text{ Nm}$$



Máquinas AC

Síncronos

Assíncronos

$$N_s = \frac{120f}{P} \quad \text{or} \quad f = \frac{PN_s}{120}$$

where N_s is the synchronous speed in *rpm*; f is the supply frequency and P is the number of poles of the machine.




Fig. 6.1 Generator principle








Fig. 6.2 Motor principle

Generator action	Motor action
	
<p align="center">Fig. 6.3 Generator action</p>	<p align="center">Fig. 6.4 Motor action</p>
<ol style="list-style-type: none"> 1. In generator action, the rotation is due to mechanical torque, therefore, T_m and ω are in the same direction. 2. The frictional torque T_f acts in opposite direction to rotation ω. 3. Electromagnetic torque T_e acts in opposite direction to mechanical torque T_m so that $\omega T_m = \omega T_e + \omega T_f$ 4. In generator action, an emf is induced in the armature conductors which circulates current in the armature when load is connected to it. Hence, e and i both are in the same direction. 5. In generator action, $E > V$ 6. In generator action, the torque angle θ is leading. 7. In generator action, mechanical energy is converted into electrical energy. 	<ol style="list-style-type: none"> 1. In motoring action, the rotation is due to electromagnetic torque, therefore, T_e and ω are in the same direction. 2. The frictional torque T_f acts in opposite direction to rotation ω. 3. Mechanical torque T_m acts in opposite direction to electromagnetic torque T_e so that $\omega T_e = \omega T_m + \omega T_f$ 4. In motoring action, current is impressed to the armature against the induced emf (e), therefore current flows in opposite direction to that of induced emf. 5. In motor action, $E < V$ 6. In motoring action, the torque angle θ is lagging. 7. In motoring action, electrical energy is converted into mechanical energy.


Como se gera uma tensão induzida variável (sinusoidal)




(a)




(b)




(c)



(d)



Relação entre frequência, velocidade de rotação e número de polos



∴ No. of cycle made per revolution = $\frac{P}{2}$

No. of revolutions made per second = $\frac{N_s}{60}$


∴ No. of cycles made per second = No. of cycles/revolution \times No. of revolutions/s

$$f = \frac{P}{2} \times \frac{N_s}{60} = \frac{PN_s}{120} \text{ cycles/s or Hz}$$


Rotor e estator

O campo magnético na máquina pode estar tanto no estator como no rotor

Nas máquinas síncronas o campo de excitação está normalmente no rotor e não no estator



Circuito equivalente de um motor síncrono



V = Voltage applied to the armature (phase value)

I = armature current (phase value)

R = effective armature resistance in ohm per phase

X_S = synchronous reactance per phase

E = excitation voltage (phase value)

Z_S = synchronous impedance per phase

I_f = exciting or field current




where, $\bar{Z}_S = R + jX_S = \sqrt{R^2 + X_S^2} \angle \tan^{-1} \frac{X_S}{R}$ ohm

$$\bar{V} = \bar{E} + \bar{I}\bar{Z}_S = \bar{E} + \bar{I}(R + jX_S) = \bar{E} + \bar{I}R + j\bar{I}X_S$$

$$\bar{E} = \bar{V} - \bar{I}\bar{Z}_S = \bar{V} - \bar{I}(R + jX_S) = \bar{V} - \bar{I}R - j\bar{I}X_S$$


Máquinas assíncronas

O estator é alimentado com corrente trifásica



Normalmente o rotor é trifásico encontrando-se os seus enrolamentos ligados em **estrela ou em triângulo**.

A ligação ao exterior é obtida através de 3 escovas que fazem contacto com cada um destes anéis.



Tal como no caso do transformador, as grandezas do rotor podem ser reduzidas ao estator e vice-versa.

Classification of electrical machines

